This item was submitted to [Loughborough's Research Repository](#) by the author.
Items in Figshare are protected by copyright, with all rights reserved, unless otherwise indicated.

Landslide research in China

PLEASE CITE THE PUBLISHED VERSION

<https://doi.org/10.1144/qjegh2016-100>

PUBLISHER

© The authors. Published by The Geological Society of London

VERSION

VoR (Version of Record)

PUBLISHER STATEMENT

This work is made available according to the conditions of the Creative Commons Attribution-NonCommercial-NoDerivatives 4.0 International (CC BY-NC-ND 4.0) licence. Full details of this licence are available at:
<https://creativecommons.org/licenses/by-nc-nd/4.0/>

LICENCE

CC BY-NC-ND 4.0

REPOSITORY RECORD

Chen, Zuyu, Xingmin Meng, Yueping Yin, Tom Dijkstra, Mike Winter, and Janusz Wasowski. 2019. "Landslide Research in China". figshare. <https://hdl.handle.net/2134/31997>.

Landslide Research in China

Zuyu Chen^{1*}, Xingmin Meng², Yueping Yin³, Tom Dijkstra⁴, Mike Winter^{5,6} and Janusz Wasowski⁷

¹*China Institute of Water Resources and Hydropower Research, Beijing, China*

²*Key Laboratory of Western China's Environmental Systems (Ministry of Education), Lanzhou University, Lanzhou, China*

³*China Institute of Geo-Environment Monitoring, China Geological Survey, Beijing, China*

⁴*British Geological Survey, Keyworth, Nottingham NG12 5GG, UK*

⁵*Transport Research Laboratory (TRL), 13 Swanston Steading, 109 Swanston Road, Edinburgh EH10 7DS, UK*

⁶*School of Earth and Environmental Sciences, University of Portsmouth, Burnaby Building, Portsmouth PO1 3QL, United Kingdom*

⁷*National Research Council, CNR-IRPI, Bari, Italy*

*Corresponding author (e-mail: chenzuyu@iwhr.com)

On 9 April 2000, a 91 Mm³ rock avalanche occurred in Linzhi Prefecture, Tibet. The event was accompanied by a deafening noise, with the rock mass traveling from a maximum elevation of 5132 m and coming to a rest at an elevation of 2163 m. It formed a landslide dam in the Yigong Zangbo River of some 55 m high impounding a reservoir of some 2 Gm³ for a period of 62 days after which it emptied in less than 12 hours (Delaney and Evans 2015). The event forewarning of a period of frequent geological disasters in China during the start of the 21st Century. The ensuing Wenchuan earthquake (surface-wave magnitude Ms 8.0; May 2008), Zhouqu debris flow (August 2010) and Ludian earthquake (Ms 6.7; August 2014) urged China to renew its campaign against geological disasters and the Chinese Government has since invested heavily in scientific research to guide efforts to mitigate the impact of such natural disasters. This thematic set on Landslide Research in China was initiated to highlight this research. This paper provides a brief review of three featured subjects and accompanies the five papers published in the thematic set.

Landslides in areas affected by earthquakes

Large earthquakes severely affect the geological environment and also result in the potential for secondary disasters in the days, months and years that follow. There is continued debate on how quickly landscapes recover following a high-magnitude disturbance. Lin (*et al.* 2006, 2009) studied the Chi-Chi Earthquake of 1999 and found that five years after the earthquake, the area experienced a relatively high number of landslides (including debris flows) followed by a trend of gradual decline. Hovius *et al.* (2011) concluded that it took approximately 6 years for the landslide signal to return to pre-1999 levels. Other examples of long-term landscape recovery are discussed in, for example, Nakamura *et al.* (2000) for the 1923 Ms 7.9 Kanto earthquake in Japan and in Huang (2011) for the 2008 Ms 8.0 Wenchuan earthquake, China. The Wenchuan earthquake took place on 12 May 2008 in Sichuan Province resulting in some 200,000 landslide events (Xu *et al.* 2013) and in the following years the province suffered frequently from further landslide activity. According to the first author's statistics, the province experienced 668, 934, 2,161, 1,997, and 3,147 geohazards from 2008 to 2012. The enhanced landslide and debris-flow activity after the 2008 Wenchuan earthquake is highlighted in the Special Issue of Engineering Geology "The long-term geologic hazards in areas struck by large-magnitude earthquakes" (2014, Volume 182, Part B).

On 24 September 2008, Beichuan County, previously destroyed by the Wenchuan Earthquake, experienced yet another debris flows which led to a further 42 fatalities (Tang and Liang, 2008; Tang *et al.* 2011a; Figure 1).

On 13 August 2010, Qingpingxiang (a town in Mianzhu County), Yingxiu (a town in Wenchuan County) and Hongkou Township (in Dujiangyan county), all severely affected by the Wenchuan Earthquake, experienced torrential floods and landslides (dominated debris flows). The total landslide volume for these regions exceeded 13 million m³ causing the partial or total destruction of roads and houses and the interruption of traffic (Figures 2 and 3).

Another serious debris flow happened on 9 July 2013 in Qipangou. The flood

disaster created a barrier lake that blocked the Mingjiang River. This is the largest recorded debris flow in this region.

Rainfall monitoring and the associated provision of timely warnings in seismically-prone regions provide an effective way of limiting the impacts of potential landslides on the local population. However, experience has shown that, as a result of long runout and high relief, the areas most impacted by landslides are not necessarily those affected by the highest intensity of rainstorms. The 7 August 2010 Zhouqu debris flow is an example (see Figure 4, Dijkstra *et al.* 2012). Zhouqu County, which was severely damaged by the debris flow, experienced a rainfall intensity of only 10 mm/h, while the Dongshantai Station, close to the top of Sanyanyu where the debris flow was initiated, registered a rainfall intensities as high as 90 mm/h (Tang *et al.* 2011b; Dijkstra *et al.* 2012; Dijkstra *et al.* 2014). Figure 5 explains the disaster process from the standpoint of a 2,000 m difference in elevation between the area of intense rainfall and the area affected by the debris flow. For this reason, the Ministry of Land and Resources launched a program to implement a warning system used in high, cold mountainous areas that experience dense fog. A remotely-operating video platform was installed in Zhouqu County, with the purpose of transmitting information to the monitoring and warning center on a real-time basis via sensors and communication satellites (Figure 6).

Geo-hazard Mitigation for the Three-Gorges Project

The Three Gorges Project is the largest hydro-electric complex both in China and the world. However, the area of the reservoir has a significant landslides history. In this area, the hilly and mountainous areas constitute 21.7% and 74% of the total, respectively while the flat surface around the dam is only 4.3%. The river valley in the reservoir area is affected by the geology, its structures and the associated geotechnical parameters. Heavy rainfall and rainstorms are frequent in the reservoir area, and about 70% of the total annual rainfall is concentrated between the months of May to September (Chen *et al.* 2005).

At the beginning of the Three Gorges Project, great efforts were made to prevent

geological disasters, including landslides, and significant effort was expended in mitigation and control works. The main experience and achievements are summarized below.

Transition from frequent geological disasters during the initial impoundment stage to the balance and decline stages.

From September 2008 to August 2014, the Three Gorges Project underwent six impoundment trials. The highest water levels in front of dam during the 2010, 2011, 2012 and 2013 trial impoundments were uniform at 175.0 m. By 31 August 2014, the reservoir area of the Three Gorges Project sustained a total of 421 significant ground deformation events and landslides, of which 120 occurred in the Hubei reservoir and 301 in the Chongqing reservoir. The total volume of landslides and collapses reached 350 million m³ and the total length of the 60 river bank slumps was 25 km. Table 1 clearly shows that in the following years, the number of slope failures declined rapidly although the water level reached the same elevation of 175 m (Zhen 2010).

After the 175m trial impoundment in 2008, the water level rose by 8.32 m from 30 October to 4 November, equivalent to 1.66 m/d. Ten days later, 37 landslides occurred at the peak level of the impoundment. Between 1 August and 6 August 2010, the cumulative decline in water level was 5.57 m, equivalent to 1.15/d, the largest daily rate of lowering since the impoundment. No landslides were generated during the ten days that followed. When the rate of lowering of the water level ranged between 0.40 m/d and 1.15 m/d, there was no correlation between the occurrence of landslides and the lowering of the reservoir water level. The first increase of the water level triggered the majority of the landslides while draw-down had little impact on landslide occurrence.

Adoption of engineering measures against major potential landslide hazards to significantly reduce the threat of geological disasters.

To ensure the safety of more than one million people living in dozens of towns surrounding the reservoir area, potentially hazardous sites were the subject of

mitigation works including drainage measures, stressed anchoring cables, anti-slide piles, etc. The hazards associated with 243 landslides sites with the potential to slide into the Yangtze River have been significantly reduced and as a result the risks to 79 towns potentially threatened either directly from landslides or from landslide-induced waves have been reduced to acceptable levels.

The surface of the bedrock landslide in central Fengjie, the Monkey Stone landslide, had an elevation of 90 m at the front-edge and 250 m at the back-edge, a 160 m elevation difference with the water level varying between 145 m and 175 m elevation as shown in Figure 7 (Chen and Feng, 2008) and occupied an area of $12 \times 10^4 \text{ m}^2$ and a volume of $450 \times 10^4 \text{ m}^3$. The engineering mitigation involved two stages (Zou *et al.*, 2008). Stage I consisted of water discharge measures, loading the toe of the slope, and erosion protection of the slope surface. Stage II extended the project and consisted of cascaded slide-resistant shear keys at the level of the slip plane, rock fill dumped underwater to further load the toe, and further slope protection and water discharge measures. The project started in May 2006 and was completed in May 2008, enhancing the safety of the population of this densely populated town as shown in Figure 8 (Chen and Feng, 2008)).

Building of systematic landslide monitoring and warning systems

The entire Three Gorges reservoir area has been built with a high-level monitoring and early-warning system that includes three levels (i.e. county, township and village levels) based on mass movement predictions, early warnings of events, and evacuation plans in order to help prevent disasters. The program aims to provide effective monitoring and warning of 3,049 sites of potential collapse, landslide and bank slump within the reservoir area. Over 12,200 people, 5,200 from the Hubei Province and 7,000 from Chongqing, have been evacuated during the period since 2003 when the reservoir was first impounded.

The landslide forecast at Qianjiangping in the Zigui County has proven to be very successful. A landslide occurred on the night of 13 July 2003 ($1,542 \times 10^4 \text{ m}^3$ volume) and caused a blockage and silting of the Qinggan River, a tributary of the

Yangtze River. However, relying on a timely warning, more than 1,200 people were safely evacuated. Table 2 presents two typical field monitoring schemes taken from a report summarizing this and 12 similar cases.

Emergency response to landslide dams

Combatting the risks associated with barrier lakes created by large-scale landslides has been one of the principal geological disaster prevention programs of China in the past 15 years.

In 2000 the Yigong-Zangbo River formed the Yigong Lake due to a mountain landslide which generated an overtopping flood of two billion m³ of water having a peak flow of 95,000 m³/s (Yin 2000). After the Wenchuan Earthquake (Ms 8.0) of 12 May 2008, the main area affected by seismic tremors saw the formation of 34 barrier lakes of different sizes. The Tangjiashan landslide lake had a storage capacity of 316 million m³ becoming the largest rainwater catchment lake with the highest impoundment and posing the most severe threat (Lin *et al.* 2010). The isograms of seismic intensity are also shown in Figure 9 which reveals a consistent trend in the distribution of earthquake-induced barrier lakes as they are clustered in the area that experienced a seismic intensity of X degrees (Cui *et al.* 2009).

In August 2010, Gansu Province was affected by very heavy rainfall with a cloudburst in the mountainous Sanyanyu and Luojiayu catchments above the town of Zhouqu triggering large debris flows. The debris flow deposits blocked the Bailong (White Dragon) river forming a barrier lake that flooded part of the town (Tang *et al.* 2011b; Yu *et al.* 2010; Dijkstra *et al.* 2012).

In 2014, an earthquake of magnitude Ms 6.5 hit Ludian County of Zhaotong in Yunnan Province and caused mountain collapses on both sides of Hongshiyan Village, blocking the Niulanjiang River and forming a barrier lake that flooded the area upstream of the Hongshiyan hydropower station (Liu 2015).

The emergency response to a barrier lake normally involves evacuating a large number of people and mobilization of large amounts of human and mechanical resources. After the Wenchuan earthquake, the Chinese government issued the

179 *Standard for Classification of Risk Grade of Barrier Lake* (SL450-2009; MWS 2009a)

180 to provide a technical and legal basis for emergency response actions. Barrier lake
181 dams were classified into several types, including high dams, narrow dams, short
182 dams, *etc.* According to the standard requirements (MWS, 2009a), the lakes are
183 classified into large size, medium size, small size (1) and small size (2) as shown in
184 Table. 3. They are then rated as extremely high risk, high risk, medium risk and low
185 risk according to Table. 4.

186 Of the 34 barrier lakes following the Wenchuan Earthquake, the Tangjiashan
187 barrier lake was classified as posing an extremely high risk, the Laoyingyan,
188 Xiaogangjian, Xiaojiaqiao and Nanba barrier lakes were classified as posing high risk,
189 with the remainder posing medium or low risks.

190 Controlled blasting is a common method of eliminating the hazard and thus
191 reducing the risk associated with barrier lakes as shown in Figure 10 (Liu et al., 2016).
192 It is usually adopted on occasions where the risk posed is judged to be significant and
193 to require urgent action: such situations include those in which recovery construction
194 works are hampered and transportation corridors required by the emergency services
195 are blocked, obstructed field construction and transportation conditions (*Technique*
196 *guideline for emergency disposal of landslide lake, SL 451-2009*; MWS. 2009b). For
197 instance, the blasting of a drainage channel followed by mechanical excavation was
198 adopted for reducing the risk associated with barrier dam outburst at three barrier
199 lakes on the Shiting River (i.e. Yanziyan, Upper Macaotan and Muguaping barrier
200 lakes), the Shibangou (Jialing River), the Ma'anshi (Fujian River basin) and the
201 Xiaogangjian (Jinyuan River) barrier lakes. Channel drainage is the most common
202 method of reducing the risk associated with barrier dam outburst both in China and
203 other countries. Other examples include the Yigong, Tangjiashan, Xiaojiaqiao and
204 Hongshiyan barrier lakes as shown in Figure 11 (Liu, et al., 2016).

206 **Landslide Research in China special set**

207 The papers published in this thematic set represent a small part of a large number
208 of scientific reports and publications on landslide research in China.

Tu and Huang (2016) present an analysis of infiltration in embankments constructed in sandy clay and gravel and evaluate the effects of rainfall intensity and duration on the stability of the embankment slopes. Their numerical analyses provide further insights into the differences in behaviour of the two materials, including a lesser sensitivity to rainfall intensity of the stability of the sandy clay slope relative to the gravel embankment slope but a larger and longer lasting reduction in slope stability of the sandy clay embankment slope for longer duration rainfall events.

Two papers provide a contribution to landslide research in the Three Gorges area. Shi *et al.* (2016) discuss landslide stability evaluation using High-Resolution Satellite SAR (Synthetic Aperture Radar) data and Huang *et al.* (2016) describe a case study of a pillar-shaped rock mass failure. Shi *et al.* (2016) used TerraSAR-X InSAR data pairs with short normal baselines and temporal baselines to map landslide-prone areas and the point-like target offset tracking (PTOT) approach to identify large displacements to characterize potential landslides. Their methods provide a clear way forward to evaluate landslide stability in this geodetically challenging terrain characterized by steep slopes and dense vegetation. Huang *et al.* (2016) describe in detail a case study of an unstable pillar-shaped rock mass in the Three Gorges area. Their calculations show that this rock mass is only marginally stable (FoS 1.08) and that the collapse of the pillar is related to local failure in a slowly deteriorating block at the foot of the pillar that is periodically affected by the 175 m impoundment level of the reservoir. Were this rock mass to fail, an estimated 360,000 m³ is likely to catastrophically enter the Yangtze forming a substantial threat to local residents and passing tourists.

The effects of the magnitude 8.0 Wenchuan earthquake on the performance of engineered interventions of the reinforced right abutment slope of the Zipingpu Dam are analysed by Ren *et al.* (2016). This 156 m high rockfill dam experienced peak ground acceleration in excess of 2g. The nearby natural slopes were severely affected by the earthquake. However, the reinforced abutment slope coped very well and a stable slope was maintained. The paper describes how this abutment slope experienced stresses and strains during the earthquake as these were monitored through multiple extensometers and load cells.

Zhou *et al.* (2016) provide a further example of monitoring and stability analysis and discuss this using a case study of the left bank slope at the Jinping-I hydropower station. This complex 530 m high excavated rock slope was instrumented with a monitoring system comprising surface deformation observations, multi-point extensometers and graphite bar extensometers. The complex geology of the site provided challenging conditions for the construction of a safe slope, particularly as it transpired that a large central section of the slope could potentially become unstable. Detailed 3D slope stability analyses assisted with the design of a stable slope and the observations from the monitoring network support the results from these design analyses.

These five papers provide a further showcase and snapshot of research currently being carried out on this topic in China and compliment the earlier thematic set on Geohazards in China (Dijkstra *et al.* 2014).

Reference

- CHEN, J., YANG, Z.F., & LI, X. 2005. Relationship between landslide probability and rainfall in Three Gorges Reservoir Area. *Chinese Journal of Rock Mechanics and Engineering*, **24**(17), 3052-3056 [in Chinese].
- CHEN, T., ZHAO, P., & WANG, K., 2014. Discussion on the formation mechanism of Liangshuijing Landslide in the Three Gorges Reservoir Area. *Journal of Engineering Geology*, **22**, 277-283 [in Chinese].
- CUI, P., ZHU, Y., & HAN, Y., 2009. The 12 May Wenchuan earthquake-induced landslide lakes: distribution and preliminary risk evaluation. *Landslides*, **6**(3), 209-22
- DELANEY, K.B. & EVANS, S.G., 2015. The 2000 Yigong landslide (Tibetan Plateau), rockslide-dammed lake and outburst flood: review, remote sensing analysis, and process modelling. *Geomorphology*, 246, pp.377-393.

- DIJKSTRA, T.A., CHANDLER, J., WACKROW, R., MENG, X.M., MA, D.T., GIBSON, A.,
WHITWORTH, M., FOSTER, C., LEE, K., HOBBS, P.R.N. & REEVES, H.J., 2012.
Geomorphic controls and debris flows—the 2010 Zhouqu disaster, China.
*Proceedings of the 11th international symposium on landslides (ISL) and the 2nd
North American Symposium on Landslides, June 2-8, 2012, Banff, Alberta,
Canada.*
- DIJKSTRA, T.A., WASOWSKI, J., WINTER, M.G. & MENG, X.M., 2014. Introduction to
geohazards of Central China. *Quarterly Journal of Engineering Geology and
Hydrogeology*, 47(3), pp.195-199.
- HOVIUS, N., MEUNIER, P., LIN, C.W., CHEN, H., CHEN, Y.G., DADSON, S., HORNG,
M.J. & LINES, M., 2011. Prolonged seismically induced erosion and the mass
balance of a large earthquake. *Earth and Planetary Science Letters*, 304(3),
pp.347-355.
- HUANG, B.L., ZHANG, Z.H., YIN, Y.P. & FEI, M., 2016. A case study of a pillar-shaped
rock mass failure in the Three Gorges Reservoir Area, China. *Quarterly Journal of
Engineering Geology and Hydrogeology*, xx(x), pp.xxx-xxx
- HUANG, R.Q. 2011. After effect of geohazards induced by the Wenchuan earthquake.
Journal of Engineering Geology, 19(2), 145-151 [in Chinese].
- LIN, C.W., LIU, S.H., & CHANG, W.S.. 2009. The impact of the ChiChi earthquake on
the subsequent rainfall induced landslides in the epicentral area of central Taiwan.
*Proceeding of International Conference in Commemoration of 10th Anniversary
of the ChiChi Earthquake*, Editor: C.C. Chen. National Science and Technology
Center for Disaster Reduction. 336-338.
- LIN, C.W., LIU, S.H., & LEE, S.Y., 2006. Impacts on the ChiChi earthquake on
subsequent rain induced landslides in central Taiwan. *Engineering Geology*, 86(2),
87-101.
- LIN, N., CHEN, Z., & ZHANG, J., 2010. Draining the Tangjiashan barrier lake. *Journal
of Hydraulic Engineering*, 136(11), 914-923.
- LIU, N. 2015. Hongshiyan Landslide Dam Danger Removal and Coordinated
Management. *Frontiers of Engineering Management*, 1(3), 308-317.

- LIU, M., YANG, Q., CHEN, Z. (CHIEF EDITOR). 2016. Hazard mitigation for barrier lakes. Yangtze River Press. Wuhan. (In Chinese).
- LU, S.Q., Y, Q.L., & YI, W., 2014. Analysis of deformation and failure mechanism of Shuping landslide in Three Gorges reservoir area. *Rock and Soil Mechanics*, **35**(4), 1123-1130 [in Chinese].
- MINISTRY OF WATER RESOURCES OF CHINA (MWS). 2009a. Standard for classification of risk grad of landslide lake. 2009. *SL 450-2009, C.F.R.* [in Chinese].
- MINISTRY OF WATER RESOURCES OF CHINA (MWS). 2009b. Technique guideline for emergency disposal of landslide lake. 2009. *SL 451-2009, C.F.R.* [in Chinese].
- NAKAMURA, H., TSACHIYA, S., & INOUE, K., 2000. Sabo against earthquakes. *Kokon Shoin*, Tokyo, Japan, 190-220.
- REN, A.W., WANG, Y.J, CHEN, Z.Y, SONG, Y.A, & SUN, P., 2016. Performance of the reinforced right abutment slope of Zipingpu Dam during magnitude 8.0 earthquake in Wenchuan, China. *Quarterly Journal of Engineering Geology and Hydrogeology*, xx(x), pp.xxx-xxx
- SHI, X.G., LIAO, M.S., ZHANG, L, & BALZ, T., 2016. Landslide Stability Evaluation using High-Resolution Satellite SAR Data in the Three Gorges Area *Quarterly Journal of Engineering Geology and Hydrogeology*, xx(x), pp.xxx-xxx
- TANG, C., & LIANG, J.T. 2008. Characteristics of debris flows in Beichuan epicenter of the Wenchuan earthquake triggered by rainstorm on September 24, 2008. *Journal of Engineering Geology*, **16**(6), 751-758 [in Chinese].
- TANG, C., ZHU, J., QI, X., & DING, J., 2011a. Landslides induced by the Wenchuan earthquake and the subsequent strong rainfall event: a case study in the Beichuan area of China. *Engineering Geology* 122, 22–33
- TANG, C., RENGERS, N., VAN ASCH, T.W., YANG, Y.H. & WANG, G.F., 2011b. Triggering conditions and depositional characteristics of a disastrous debris flow event in Zhouqu city, Gansu Province, north-western China. *Natural Hazards and Earth System Sciences*, **11**(11), pp.2903-2912.

- TU, G.X. & HUANG, R.Q 2016. Infiltration in two types of embankments and the effects of rainfall time on the stability of slopes. *Quarterly Journal of Engineering Geology and Hydrogeology*, xx(x), pp.xxx-xxx
- XU, C., XU, X., YAO, Q. & WANG, Y., 2013. GIS-based bivariate statistical modelling for earthquake-triggered landslides susceptibility mapping related to the 2008 Wenchuan earthquake, China. *Quarterly Journal of Engineering Geology and Hydrogeology*, 46(2), pp.221-236.
- YIN, Y. 2000. Rapid huge landslide and hazard reduction of Yigong River in the Bomi Tibet. *Hydrogeology and Engineering Geology*, 4, 8-11 [in Chinese].
- YU, B., YANG, Y., & SU, Y., 2010. Research on the giant debris flow hazards in Zhouqu County, Gansu Province on August 7, 2010. *Journal of Engineering Geology*, 18(4), 437-444 [in Chinese].
- ZHEN, S.R., 2010. Some Considerations on trial impoundment operation of Three Gorges Project at 175m water level. *Yangtze River*, 41(8), 1-4 [in Chinese].
- ZHOU, C.B., JIANG, Q.H., WEI, W., CHEN, Y.F. & RONG, G., 2016. Safety monitoring and stability analysis of left bank high slope at Jinping-I hydropower station. *Quarterly Journal of Engineering Geology and Hydrogeology*, xx(x), pp.xxx-xxx
- CHEN, Z. & FENG, M. (CHIEF EDITOR). 2008. Engineered slopes in china - approaches and case studies. China Three Gorges Press. yichang.
- ZOU, C.L., ZHENG, X., & XIONG, C. Y., 2008. Design of control works for Houzishi landslide in Three Gorges area. *Yangtze River*, 39(6), 57-61 [in Chinese].

Tables

Section	2008	2009	2010	2011	2012	2013	2014	Total
Chongqing reservoir area	243	16	12	11	11	5	3	301
Hubei reservoir area	90	5	12	5	4	2	2	120
Entire reservoir area	333	21	24	16	15	7	5	421

Table 1 Annual landslide events as a result of 175m trial impoundments from September 2008 until September 2014.

Size of barrier lake	Barrier lake storage capacity V (10^8 m^3)
Large size	$V \geq 1.0$
Medium size	$1.0 > V \geq 0.1$
Small size (1)	$0.1 > V \geq 0.01$
Small size (2)	$V < 0.01$

Tab. 2 Classification of barrier lakes by size.

Risk grade	Grading index		
	Size of barrier lake	Material composition of the landslide dam	Height of the landslide dam (m)
Extremely high risk	Large size	Mainly soil	>70
High risk	Medium size	soil containing large rock blocks	$30 \sim 70$
Medium risk	Small size (1)	Large rock blocks containing soil	$15 \sim 30$
Low risk	Small size (2)	Mainly large rock blocks	<15

Tab. 3 Risk factors of barrier lakes.

358

359

360

Fig. 1 A view of Beichuan County town shortly after it was buried by the Weijiagou landslide of the 24th of September 2008

Fig. 2 Aerial photo of the August 13th landslide in Qingpingxiang Town, Mianzhu. Along a 3km section through Qingpingxiang more than ten valleys saw the outbreak of simultaneous mudslides and debris flows.

Fig. 3 The market town of Qingpingxiang covered by silt and buried by the “8.13” torrent and mudslide. The mudslide volume reached 6,000,000m³ and far exceeded that of the Zhouqu mudslide (i.e. 1,800,000m³) (Extracted from www.nandu.com).

Fig. 4 Cumulative rainfall recorded at the rainfall stations in Zhouqu and Dongshantai (from Dijkstra *et al.* 2012).

Fig. 5 A longitudinal section of the Dayu valley, one of the tributaries to the Bailong River draining the Sanyanyu catchment where the Zhouqu debris flow originated. Steps in the longitudinal profile are predominantly formed by palaeo-rock avalanches. The critical change in behaviour occurred at an altitude of 2300 m; above this level discharge is characterized by turbulent flow and large bedload transport, while below this step in the terrain the torrent regime changed, eroded substantial quantities of valley-based deposits and took on the characteristics of a debris flow (modified after Dijkstra *et al.* 2012)

Fig. 6 Geological disaster monitoring and warning apparatus used in cold alpine and densely-fogged mountainous areas.

Fig. 7 The Monkey Stone landslide prevention and control projects and relocated households in Fengjie County. The red line indicates the outline of the landslide.

Fig. 8 Layout profile of the prevention and control project of the Monkey Stone landslide
(See also Figure 7).

Fig. 9 Two case studies of typical geological disasters as a result of a 175 m impoundment in the Three Gorges Reservoir (Chen et al. 2014; Lu et al. 2014).

Fig. 10. Diagram showing the location of the barrier lakes related to the Wenchuan Earthquake. The Roman numerals represent the earthquake intensity.

Fig. 11 The large volume of material generated by the Zhouqu debris flow blocked the Bailong river, causing extensive upstream flooding. Explosives were used to enlarge drainage channels during the first phase of the emergency response mission.

Fig. 12 Excavation of a drainage channel at the Hongshiyuan barrier lake during the first phase of the emergency response mission.