

Figure S1




Figure S1. Specimen failure of human cadaver bone. (A) Fracture of palmar cortex. **(B)** Fracture at bone/PMMA interface. PMMA = poly(methyl methacrylate).